

Appendix C Photographs of Delta Levees (Chapter 5)

List of Figures

Figure C-1 Sacramento River south of Courtland, showing repair of erosion using rip-rap	2
Figure C-2 - Merritt Island, showing repair of erosion site using vegetation	3
Figure C-3 - Sutter Slough, showing natural vegetation on levees	4
Figure C-4 - Sargent-Barnhart Tract, with Brookside Subdivision mansions behind levee.....	5
Figure C-5 - McDonald Island, with PG&E gas storage facilities behind levee	6
Figure C-6 - Mildred Island, showing effect of flooding on levee	7
Figure C-7 - Upper Jones Tract, showing repair of 2004 breach with eco-bench.....	8
Figure C-8 - Byron Tract, showing stepped seismically-resistant levee.....	9
Figure C-9 - McDonald Island, showing PL 85-99 berm on landside.....	10
Figure C-10 - Steamboat Slough	11

Figure C-1 Sacramento River south of Courtland, showing repair of erosion using rip-rap



Figure C-2 - Merritt Island, showing repair of erosion site using vegetation



Figure C-3 - Sutter Slough, showing natural vegetation on levees



Figure C-4 - Sargent-Barnhart Tract, with Brookside Subdivision mansions behind levee



Figure C-5 - McDonald Island, with PG&E gas storage facilities behind levee



Figure C-6 - Mildred Island, showing effect of flooding on levee



Figure C-7 - Upper Jones Tract, showing repair of 2004 breach with eco-bench



Figure C-8 - Byron Tract, showing stepped seismically-resistant levee




Figure C-9 - McDonald Island, showing PL 85-99 berm on landside



Figure C-10 - Steamboat Slough

