NOTE:
Classifications may not reflect changes due to recent levee work if DWR did not have the post-construction survey file in its possession. Not all District levees may be shown on these maps.

	SECTIONS	MILES ANALYZED
BELOW HMP	1	0.19
MINIMALLY BELOW HMP	2	0.38
HMP BUT BELOW PL84-99	44	8.33
PL84-99	72	13.64
TOTAL	119	22.54



Levee Assessment - RD 563 - Tyler Island

0 0.5 1 2 Miles