



NOTE:
 Classifications may not reflect changes due to recent levee work if DWR did not have the post-construction survey file in its possession. Not all District levees may be shown on these maps.

Legend

LEVEE STATUS

- BELOW HMP
- MINIMALLY BELOW HMP
- HMP
- PL8499

	SECTIONS	MILES ANALYZED
BELOW HMP	0	0.00
MINIMALLY BELOW HMP	0	0.00
HMP BUT BELOW PL84-99	1	0.19
PL84-99	15	2.84
TOTAL	16	3.03

Levee Assessment - RD 1608 - Lincoln Village West

